

DIRECTIVE: Fix the minor erosion on both sides of the rip-rap lined inlet forebay area.

