

Annual Inspection Report



NEW CASTLE COUNTY DEPARTMENT OF PUBLIC WORKS
187-A OLD CHURCHMANS ROAD
NEW CASTLE, DE 19720

Inspector's Name:	PETROWSKY, JULIE E	Parcel #:	0802730064
Inspection Date:	06/16/2021	Latitude:	39.75
Unit ID: 11036	Cond Code: 3 Minor	Longitude:	-75.64
Name:	Greenville Overlook 11 BasinB2	Facility Type:	Dry Pond
Location:	131 ODYSSEY DR WILMINGTON, DE 19808	Outlet Structure:	Concrete Weir
Contact:	GREENVILLE OVERLOOK MAINTENACE CORP C/O ASPEN PROPERTY MGT PO BOX 858 ELKTON, MD 21922	Ownership:	PRIV
		As-Built:	Yes
		Type of Site:	RES
		Council District:	2
		Inspection #:	320210
		Type of Discharge:	Creek

SUMMARY OF INSPECTION ACTIVITY FOR THE YEAR 2021

DATE

COMMENTS

8/31/21 Owner received a Notice of Violation Warning in 2020. A Notice of Violation is being sent since all or some of the maintenance deficiencies noted in the 2020 inspection report still exist and need to be corrected.

Inspected By:

To verify completion of the necessary maintenance, please send before and after photos to Julie.Petrowsky@newcastlede.gov, or call Julie Petrowsky at 302-395-5795

*NOTE: Days to correct are calculated from the date you receive this report.

Inspection Results

OBSERVATIONS	RESULTS	COMMENTS
ACCESS		
10FT ACCESS PATH TO FACILITY (MOWED)	GOOD	
ACCESS PATH AROUND INLETS	GOOD	
ACCESS PATH AROUND OUTLETS	GOOD	
ACCESS PATH AROUND EMERGENCY SPILLWAY	GOOD	
ACCESS PATH AROUND OUTFALL	GOOD	
EROSION CONTROL		
LOW FLOW CHANNEL	N/A	
TOP OF SLOPE	GOOD	
SIDE SLOPE AND BUFFER	GOOD	
INLET STRUCTURES OR CHANNELS	GOOD	
OUTLET CHANNEL	FAIR	Fix the minor erosion along the back side of the outlet structure.
EMERGENCY SPILLWAY	GOOD	
OUTFALL	GOOD	
SEDIMENT ACCUMULATION		
LOW FLOW CHANNEL	N/A	
INLET STRUCTURES OR FOREBAY	FAIR	Remove the minor sediment/vegetation/debris throughout the rip-rap lined inlet forebay area.
OUTLET STRUCTURES OR FOREBAY	FAIR	Remove the minor sediment/vegetation/debris from on and around the outlet structure.
OUTFALL STRUCTURES OR FOREBAY	FAIR	Remove the minor sediment/vegetation/debris throughout the rip-rap lined outfall forebay.
EMERGENCY SPILLWAY	GOOD	
RISER CONDITION		
CONCRETE RISER	N/A	
METAL RISER	N/A	
PLASTIC RISER	N/A	
TRASH RACK	FAIR	Remove minor debris deposits from each trash rack on the outlet structure.
STRUCTURAL CONDITION		
INLET	GOOD	
OUTLET	GOOD	
OUTFALL	GOOD	
EMERGENCY SPILLWAY	GOOD	
MONITORING WELLS	N/A	

GENERAL CONDITION		
RIPRAP CONDITON	GOOD	
WEATHER CONDITIONS	PRECIPITATION LAST 48 HRS	
TYPE OF LOW FLOW STRUCTURE	ORIFICE	Remove the dead vegetation and debris from around the low flow orifice.
TRASH & LITTER IN BMP	NO	
INADEQUATE VEGETATION COVER	NO	
UNWANTED BIKE TRAILS OR ANIMAL BURROWS	NO	
BUFFER	NO	
NOXIOUS WEEDS/UNWANTED TREES	NONE	
OVERALL BMP CONDITION	3 Minor	
OTHER		